

TELMAR NETWORK TECHNOLOGY MULTI-VENDOR REPAIR PROGRAM

In today's economy, carriers are looking for ways to preserve and extend the life of their network. With Telmar Network Technology as your multi-vendor repair partner, not only can you extend the life of your communications network, you'll also achieve significant OPEX and CAPEX savings.

Telmar Network Technology is the market leader in delivering multi-vendor, network-wide repair to global service providers, OEMs and enterprises around the world. Our diverse portfolio of repair capabilities includes more than 70,000 parts of Wireless, Wireline, Enterprise, Customer Premise Equipment (CPE) and test equipment. Not only will you be able to speed up your repair turnaround time, you'll also be able to save money and time by having one repair partner for your multi-vendor repair needs.

Our multi-vendor repair solutions help shorten the turnaround time because we understand how critical it is to keep your network operating and servicing your customers. While an OEM will normally turn around standard repairs in 45 days, Telmar's standard repair solution is completed within 15 days or less.

GLOBAL MULTI-VENDOR WIRELESS REPAIR

Six years ago, Telmar Network Technology joined forces with its subsidiary, Commnet Supply, to offer a full range of products and services to wireless carriers. Together, Telmar and Commnet Supply offer turnkey solutions for 3G (CDMA, EVDO Rev A, GSM Edge and UMTS) and 4G (LTE and WiMAX) networks across North America, Central America and Latin America including:

- Multi-vendor, network-wide repair
- Certified pre-owned equipment
- New equipment from leading manufacturers
- Spare parts management programs
- Global professional services

Telmar offers multi-vendor repair for access, switching and transport gear at our world-class repair facilities, including:

	UMTS	CDMA	GSM	SWITCHES
NORTEL		Metrocell 3030 BSC 3031 TCU	ECELL S8000 BSC S12000 TCU	DMS
LUCENT	Modcell 4.0 Node B	Modcell 1.0 Modcell 2.0 Modcell 3.0		5ESS
NOKIA	Flexi		Flexi Ultrasite	DX200
SIEMENS			BS60 BS240	
ERICSSON	RBS3106 RBS3206		RBS2101 OD RBS2102 ID/OD RBS2202 ID RBS2205 ID RBS2206 ID RBS2207 ID Maxite RBS2301 ID/OD RBS2302 ID/OD RBS2308 OD RBS2401 ID RBS2106 OD	AXE10

Corporate Headquarters

901 Jupiter Road
Plano, TX 75074

Repair Facilities

901 Jupiter Road
Plano, TX 75074

7710 N. 30th St.
Tampa, FL 33610

info@telmarnt.com
866.TELMARNT
(866.835.6276)

For More Information
About Telmar's Multi-
Vendor Repair Programs
Visit www.telmarnt.com.